



This photograph of the Upper Reservoir is the view looking north from the dam. The vineyard around the north side of the reservoir was not included in the licensed place of use.



Pump at the toe of the Upper Reservoir dam.



This photograph shows the spill pipe in the Upper Reservoir's dam on the day of the inspection.



This photograph, taken after the inspection (about April 2002), was provided by the licensee and shows the spill pipe after it was lowered. The new elevation is not certain. Lowering it 4.5 feet from the inspected level would bring the capacity within compliance with the license. Lowering it 2.5 feet may only put the dam outside the jurisdiction of the Division of Safety of Dams.



The Middle Reservoir looking north from the dam.



The spillway at the Middle Reservoir looking south.



The Upper Reservoir looking west across the dam. Note the spill pipe in the left side of the photograph. The former spillway observed at licensing has been filled.



The circle drawn on this photograph of the Upper Reservoir dam shows the location of the old spillway.



This photograph of the Upper Reservoir is the view looking north from the dam. The vineyard around the north side of the reservoir was not included in the licensed place of use.