

Appendix E Photo Documentation

This page intentionally left blank.



PHOTO 1:

View of effluent polishing channel from discharge point, facing east.

Photo taken on June 3, 2015.



PHOTO 2:

View of current discharge within effluent polishing channel feature within the existing WWTP footprint.

Photo taken on June 3, 2015.



PHOTO 3:
View of northeast corner of primary construction site within recently disturbed developed habitat within the existing WWTP footprint.

Photo taken on June 3, 2015.



PHOTO 4:
View of existing WWTP Pond No. 1 and proposed location for recycled water storage pond and pump within the existing WWTP footprint.

Photo taken on June 3, 2015.



PHOTO 5:

View of existing WWTP Pond No. 1 and access roads proposed for construction of recycled water storage pond and pump facilities within the existing WWTP footprint.

Photo taken on June 3, 2015.



PHOTO 6:

View of primary proposed construction zone within existing developed habitat within the existing WWTP footprint.

Photo taken on June 3, 2015.



PHOTO 7:
View of proposed location for new retaining wall, facing south within the existing WWTP footprint.

Photo taken on June 3, 2015.




PHOTO 7:
View of existing cliff swallow nest observed on a building within the existing WWTP footprint.

Photo taken on June 3, 2015.