

## IMPERIAL IRRIGATION DISTRICT MEMORANDUM

To: Elston Grubaugh, Manager, Resource

Planning and Management

Copy: FILE

**Date:** May 22, 2002

From: Supervisor, Environmental

Compliance

**DEPARTMENT:** General Services

**SUBJECT:** Salton Sea Dike Photos

I have had a chance to look at the photographs contained in IID Exhibits 67 and 68. This memorandum provides background information on the subject matter, date, location, and photographer of each photograph.

IID Exhibit 67:

#1 Subject Matter:

Concrete Block Warehouse and Power Pole.

Date:

October 11, 2001

Location:

Salton Sea Beach

Photographer:

Michel D. Remington, Supervisor, Environmental

Compliance

#2

Subject Matter:

Structure of unknown use with attached boat dock.

Date:

1995

Location:

Salton City

Photographer:

Randal Stocker, Manager, Planning and Technical

Services

#3

Subject Matter:

Commercial Lots.

Date:

Early 1970's

Location:

Unknown

Photographer:

Obtained by Randal Stocker, Manager, Planning

and Technical Services

#4

Subject Matter:

Residential Structure.

Date:

1995

Location:

Unknown

Photographer:

Randal Stocker, Manager, Planning and Technical

Services

#5

Subject Matter:

Residential Structure.

Date:

October 11, 2001

Location: Photographer: Salton Sea Beach Michel D. Remington, Supervisor, Environmental

Compliance

#6

Subject Matter:

Hardware Store.

Date:

October 11, 2001

Location:

Salton Sea Beach

Photographer:

Michel D. Remington, Supervisor, Environmental

Compliance

#7 Subject Matter: Trailor Park at Desert Shores.

Date: 1995

Location: Salton Sea Beach

Photographer: Unknown

#8 Subject Matter: Trailor Park at Desert Shores.

Date: 199

Location: Salton Sea Beach

Photographer: Unknown

#9 Subject Matter: Trailor Park at Desert Shores.

Date: 1995

Location: Salton Sea Beach

Photographer: Unknown

#10 Subject Matter: Trailor Park at Desert Shores.

Date: 1995

Location: Salton Sea Beach

Photographer: Unknown

IID Exhibit 68:

#1 Subject Matter: Dike Reconstruction.

Date: 1995

Location: Lack Road at southern end of the Salton Sea.

Photographer: Michel D. Remington, Supervisor, Environmental

Compliance

#2 Subject Matter: Dike Reconstruction.

Date: 1995

Location: Lack Road at southern end of the Salton Sea.

Photographer: Michel D. Remington, Supervisor, Environmental

Compliance

#3 Subject Matter: Dike Reconstruction.

Date: 1995

Location: Lack Road at southern end of the Salton Sea.

Photographer: Michel D. Remington, Supervisor, Environmental

Compliance

#4 Subject Matter: Dike Reconstruction.

Date: 1995

Location: Lack Road at southern end of the Salton Sea.

Photographer: Michel D. Remington, Supervisor, Environmental

Compliance

#5 Subject Matter: Dike Reconstruction.

Date: 1995

Location: Lack Road at southern end of the Salton Sea.

Photographer: Michel D. Remington, Supervisor, Environmental

Compliance

#6 Subject Matter: Dike Reconstruction.

Date: 1995

Location:

Lack Road at southern end of the Salton Sea.

Photographer:

Michel D. Remington, Supervisor, Environmental

Compliance

#7

Subject Matter:

Geothermal Plants.

Date: Location:

Lack Road at southern end of the Salton Sea.

Photographer:

Randal Stocker, Manager, Planning and Technical

Services

#8

Subject Matter:

Geothermal Plants.

Date:

Date.

1995

Location:

Lack Road at southern end of the Salton Sea.

Photographer:

Randal Stocker, Manager, Planning and Technical

Services

MICHEL D. REMINGTON