

Exhibit MMR-04

Photographs of the Hydorelectric Power Plant



Exhibit MMR-04 Photograph #1 – The hydroelectric powerplant in September 2016

The additional photograph included in this Exhibit MMR-04 was part of the 20 November 2013, Marble Mountain Ranch Water Rights Investigation Report prepared by Cascade Stream Solutions, LLC



Photograph 4. Micro-hydro power plant diversion flows enter from the pipes on the left of the photograph. Heated effluent from the heat sink resistor is visible near the top of the photograph near the roof beam.