

Exhibit MMR-06

Photographs of the Outfall to the Irving Creek Tributary and Confluence of Outfall with Irving Creek from Spring 2017

No water was discharged from Marble Mountain Ranch during Spring 2017, the photographs demonstrate that all points of the outfall were dry during this time



Exhibit MMR-06 Photograph #1 – End of Marble Mountain Ranch return flow channel to Irving Creek outfall showing no flow present in spring 2017



Exhibit MMR-06 Photograph #2 – Headcut of Irving Creek outfall showing no flow present in spring 2017



Exhibit MMR-06 Photograph #3 – Confluence of outfall water and Irving Creek showing no flow into Irving Creek from Marble Mountain Ranch in spring 2017