

Exhibit MMR-08

Photographs of Screen and Box Culvert in Diversion before entering Treatment and Hydroelectric System



Exhibit MMR-08 Photograph #1 – screened portion of diversion and culvert before water in the diversion moves to treatment and hydroelectric systems



Exhibit MMR-08 Photograph #2 – a culverted portion of the diversion just before the water meets the screened portion of the diversion



Exhibit MMR-08 Photograph #3 – A screen within the diversion hat is regularly cleaned and cleared of debris

The additional photograph included in this Exhibit MMR-08 was part of the 20 November 2013, Marble Mountain Ranch Water Rights Investigation Report prepared by Cascade Stream Solutions, LLC



Photograph 7. Forebay to pressurized system. Flows enter system through the screen in the half pipe section.