

**Lake Madrone Water District
Photos to Accompany Alternative Compliance Plan
for Permit 21027 (Application 30657)**



Madrone Lake Dam intake to siphon-spillway structure and staff gage (photo date June 1, 2013).



Staff gage mounted on headwall at siphon-spillway structure (photo date June 1, 2013).

**Lake Madrone Water District
Photos to Accompany Alternative Compliance Plan
for Permit 21027 (Application 30657)**



Madrone Lake Dam low-level outlet gate control; embankment dam at right, siphon-spillway structure in background (photo date October 14, 2014).



Madrone Lake Dam low-level outlet gate control (photo date October 14, 2014).

**Lake Madrone Water District
Photos to Accompany Alternative Compliance Plan
for Permit 21027 (Application 30657)**



Lake Madrone Dam low-level outlet discharge on downstream side of dam, with control valve (photo date October 10, 2014).