

## **San Juan Hills Golf Course Maintenance Area, 32120 San Juan Creek Road, San Juan Capistrano, California**

*Staff Contact: Joe Whearty*

The San Diego Water Board intends to issue a no further action letter for investigation of petroleum hydrocarbons detection in a sump adjacent to the San Juan Hills Golf Course Maintenance Area (Golf Course) located at 32120 San Juan Creek Road, San Juan Capistrano, California. Multiple rounds of groundwater and soil sampling have indicated that the source for the petroleum hydrocarbons detection does not originate from the Golf Course. The actions taken by the Golf Course fulfil the requirements stated in Investigative Order No. R9-2024-0088 issued by the San Diego Water Board on October 4, 2024.

Investigation documents including reports, site visit notes, and Investigative Order can be found on the GeoTracker website:

[San Juan Hills Golf Club GeoTracker Link](#)

The 14-day public notification period ends on February 4, 2026. Any comments provided regarding this matter will be considered by the San Diego Water Board. The case files are available for public review by submitting a file review request to the San Diego Water Board office, or on-line from the GeoTracker database.

Provided no significant issues arise during the public notification period, the San Diego Water Board will issue a no further action letter after the completion of site monitoring well destruction and waste removal from the site by the responsible party.

For questions or comments, please contact Joe Whearty by phone at 619-521-3357, or by email at [Joe.Whearty@waterboards.ca.gov](mailto:Joe.Whearty@waterboards.ca.gov)