


CONTACT REPORT
STATE WATER RESOURCES CONTROL BOARD
DIVISION OF WATER RIGHTS

From: 
Larry Lindsay, Compliance Unit

Contact: Peter Sagues, agent for Vineyard Club (707) 857-4175

Date: August 16, 2005

Re: A026224

Mr. Sagues called and asked about the inspection results, because when I conducted the inspection I told him we would follow-up with a letter describing the results. I told Mr. Sagues we have not sent the letter yet because the Division is considering enforcement action due to Vineyard Club's violation of the requirement to maintain a measuring device to measure bypass flow. I suggested that he should proceed with correcting the violation. I also told him that a registered engineer should design the measuring device and certify that it is properly installed. Mr. Sagues asked me to FAX a copy of the license to him and I did so.

Immediately following the inspection on May 4, 2005, before I left the property, I had already told Mr. Sagues that enforcement action was possible and that he needed to correct the discrepancy as soon as possible. Therefore, in my opinion, I did not tell him anything in this conversation that I had not already told him on May 4, 2005.