



**Legend**

- Monitoring Well Location - Active & Abandoned  
MW6
- Cuesta Geotechnical Soil Excavation Sample Site  
Sites 01 - 06 & 1w - 8w    sidewall samples  
Sites 1b - 7b                    base samples
- SEACOR Test Sites - 1994
- A - A'    Cross-section location

Paso Robles Street



Cuesta Geotechnical                    San Luis Obispo, CA  
An Environmental Service                    (805) 543-4084

Dewar Property / UST Leak Site  
840 Paso Robles Street  
Paso Robles

Item No. 3 Attachment No. 2  
September 7-8, 2006 Meeting  
Low Threat and General  
Discharge Cases

Scale: 1 inch = 60 feet