



Perchlorate Results – Upper Deep Aquifer
 First Quarter 2009 Groundwater Monitoring Report
 Olin/Standard Fusee Site
 Morgan Hill, California

FIGURE
3.4

DRAWN TJH	JOB NUMBER 6107090013 06	CHECKED	CHECKED DATE 4/2009	APPROVED	APPROVED DATE
--------------	-----------------------------	---------	------------------------	----------	---------------