



Offsite Perchlorate Results in the Intermediate Aquifer
 First Quarter 2006 Groundwater Monitoring Report
 Olin/Standard Fusee Site
 Morgan Hill, California

FIGURE

23

DRAWN
TJH

JOB NUMBER
6300060006 01.0

CHECKED

CHECKED DATE
4/2006

APPROVED

APPROVED DATE

4-28-06