Central Coast Regional Water Quality Control Board
Prosecution Team Evidence
in the matter of
Cease and Desist Order R3-2016-0015
Exhibit 18

Inspection ID: 22823386 Date Printed: 02/04/2016

FACILITIES INSPECTION REPORT

Region/Office: 3	Status: Performed	Reg. Measure ID:	388398
Program Type: WDRNONMUNIPRCS	WDID: 3 401212496	Order Number:	97-010-DWQ
Scheduled Insp. Date:	Actual Insp. Date:	12/16/2015	

Discharger Information

Party ID: 537898 Discharger Organization Name:	Centrally Grown Holdings LLC
Address: 15821 Ventura Boulevard 490	City, State, Zip: Encino, CA 91436
Discharger Contact Person:	Discharger Contact Phone:

Facility Information

Place ID 788896 Facility Name: Centra	lly Grown, Inc Small Onsite Treatment System	
Address: 7432 Exotic Gardens Drive	City, State, Zip: Cambria, CA 93428	
County: San Luis Obispo Latitude: 35.58742	Longitude: -121.12107 Method: Address Matching	

Lead Inspector Information

Lead Inspector Party	ID: 147245	Lead Inspector Name: Jon Rokke
Inspector Type:	State	☐ State Contractor ☐ EPA Contractor ☐ EPA (Regional)
	☐ EPA and St	tate (EPA Lead)

INSPECTION TYPE (Check One)

"A" type compliance - Comprehensive inspection in which samples are usually taken (EPA Type S)
AGT SPCC - An inspection of an above ground tank site and review of the site's spill prevention control and counter measure plant.
"B" type compliance - A routine inspection (EPA Type C) that typically does not include collecting samples
Complaint - Inspection made in response to a complaint
Field Oversight - Inspection or site visit to confirm clean-up work is being performed
Follow-up (enforcement) - Included inspections specifically made to verify compliance with enforcement mandates
Follow-up (non-compliance) - Includes inspections specifically made to verify corrections of non-compliance where no enforcement has been initiated
Pre-requirement - Inspection made to gather information relative to preparing, modifying, or rescinding requirements
Pretreatment Compliance Audit - An audit that includes review of that program authority, records, and industrial facility field inspections
Pretreatment Compliance Inspection - An inspection of a pretreatment program that includes records review and industrial facility field inspections
MS4 Audit - An evaluation of an MS4 program or program component that could possibly lead to enforcement. It must include a site visit.
NOT - Inspection performed in response to the submittal of a Notice of Termination coverage under a general order
Miscellaneous - Any inspection type not mentioned above

VIOLATIONS

Date Printed: 02/04/2016

Were Violations noted	during this insu	pection? \square Yes	■ No
vvcic violations noted	adming time map		

Violation ID	Violation Type	Occurrence Date	Rank	Description
		Date		
	NCDECTION	CUNANAA	DV /D)
			_	REQUIRED) (500 character limit)
Follow-up found lower portion of drain-field still not connected or replaced as specified in NOV response. Monitoring lab sheets submitted for November - monitoring report incomplete and missing BOD/CBOD parameters. Informed Owner and staff that enforcement actions are coming if they dont start complying with all aspects of permit.				
	GENERAL	NOTES (OPTI	ONAL) (2000 character limit)
				comply before potential January 28-29 hearing. Facilities
manager frustrated with owner not funding required actions.				
For Internal Use (Optional)				
Reviewed I	-	Regio	(2 onal Boa	
Date:	7		lumber:	

Centrally Grown Inspection 12-16-15



Saturated Disposal Field 12-16-15



Sagging Fence and Saturated Soils 12-16-15