

## Exhibit 4

### Victorville Old Town Depth to Groundwater Elevations

Site	Location	Date Monitored	Ground Water Elevation (MSL) (feet)		Depth to Water (BGS) (feet)		Reference
			Min.	Max.	Min.	Max.	
Former Nuway Dry Cleaners	15595 8th Street	11/24/2014	2705.65	2707.99	24.89	27.11	1
Former Chevron Bulk Plant	16928 D Street	9/12/2012	2701.59	2707.14	12.53	17.48	2
Golden West Tire	16568 D Street	2/12/2008	2705.58	2705.86	4.38	5.51	3

#### Notes

MSL - mean sea level

BGS - below ground surface

#### References

1. Groundwater Investigation Report, January 30, 2015. Prepared by Ninyo & Moore.
2. Third Quarter 2012 Semiannual Groundwater Monitoring Report, October 29, 2012. Prepared by Holguin, Fahan & Associates
3. Quarterly Groundwater Monitoring Report, February 12, 2008. Prepared by EarthSafe.