

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD - SAN DIEGO REGION
WATERSHED MANAGEMENT PROGRAM

FILE

FACILITY INSPECTION REPORT

INSPECTION DATE: 10/28/05

Time: 930

WDID/File No. 937C337203

FACILITY: Carlsbad Municipal Golf Course

FACILITY REPRESENTATIVE(S) PRESENT DURING INSPECTION: Eric Becker (SDRWQCB) Ben Neil (SDRWQCB), John Przybysewski (Heinbuch Golf LLC) Conrad Hammond (City of Carlsbad)

The City of Carlsbad NAME OF OWNER, AGENCY OR PARTY RESPONSIBLE FOR DISCHARGE	Mr. John Cahill (760) 602-2726 OWNER CONTACT NAME AND PHONE #
Heinbuch Golf LLC FACILITY OR DEVELOPER NAME (if different from owner)	Mr. John Przybysewski (714) 815-1799 FACILITY OR DEVELOPER CONTACT NAME AND PHONE #
5800 Hidden Valley Road FACILITY STREET ADDRESS	Carlsbad, CA 92009 FACILITY CITY AND STATE

APPLICABLE WATER QUALITY LICENSING REQUIREMENTS

- MS4 URBAN RUNOFF REQUIREMENTS NPDES NOS. CAS0108758, CAS0108740 or CAS0108766
- GENERAL PERMIT ORDER NO. 99-08-DWQ, NPDES NO. CAS000002 - CONSTRUCTION
- GENERAL PERMIT ORDER NO. 99-06-DWQ, NPDES NO. CAS000003 - CALTRANS
- GENERAL OR INDIVIDUAL WASTE DISCHARGE REQUIREMENTS
- GENERAL OR INDIVIDUAL WAIVER OF WASTE DISCHARGE REQUIREMENTS
- SECTION 401 WATER QUALITY CERTIFICATION
- CWC SECTION 13264

INSPECTION TYPE (Check One)

- A1 ___ "A" type compliance--Comprehensive inspection in which samples are taken. (EPA Type S)
- B1 ___ "B" type compliance--A routine nonsampling inspection. (EPA Type C)
- 02 X Noncompliance follow-up--Inspection made to verify correction of a previously identified violation.
- 03 ___ Enforcement follow-up--Inspection made to verify that conditions of an enforcement action are being met.
- 04 ___ Complaint--Inspection made in response to a complaint.
- 05 ___ Pre-requirement--Inspection made to gather info. relative to preparing, modifying, or rescinding requirements.
- 06 ___ No Exposure Certification (NEC) - verification that there is no exposure of industrial activities to storm water.
- 07 ___ Notice of termination request for industrial facilities or construction sites - verification that the facility or construction site is not subject to permit requirements (Type, NOT I or NOT C - circle one).
- 08 ___ Compliance Assistance Inspection - Outreach inspection due to discharger's request for compliance assistance.

INSPECTION FINDINGS

- N Were violations noted during this inspection? (Yes/No/Pending Sample Results)
- N Were samples taken? (N=no) If YES then, G= grab or C= Composite and attach a copy of the sample results/chain of custody form

- I. COMPLIANCE HISTORY:
 - 1st inspection on 10/14/2005
 - 2nd Inspection on 10/18/2005

FACILITY: Carlsbad Municipal Golf

WDID/File #: 337203

INSPECTION DATE: 10/28/05

II. FINDINGS:


- Additional erosion and sediment control BMPs were being installed at the site at the time of the inspection.
- Straw erosion control blankets were being installed on some exterior slopes. Additional straw blankets and other erosion control BMPs will be available to cover all exterior slopes prior to rain events (Photo 3).
- New silt fence has been installed along the entire perimeter (Photo 2)
- Sediment traps have been sized and constructed in inactive areas (Photo 1). Sediment traps have been designed/sized and will be installed prior to rain events.
- City of Carlsbad and its environmental consultant Dudek & Associates will oversee work by the new erosion control contractor and ensure implementation of BMPs in active areas as part of the site's weather triggered action plan.
- The existing SWPPP will include all these BMP changes.
- I informed City of Carlsbad personnel that additional BMPs will need to be stockpiled on-site for implementation.

III. RECOMMENDATIONS AND ADDITIONAL COMMENTS:

- Provided the City maintains existing BMPs and implements their weather triggered action plan, the site should have adequate BMPs to reduce/eliminate further discharges of sediment.
- Additional stockpiled BMPs are needed on site to ensure implementation during rain events.

IV. SIGNATURE SECTION

Inspection Report
received by :

FACILITY REPRESENTATIVE	SIGNATURE	TITLE	DATE
Eric Becker STAFF INSPECTOR			10/28/2005

VI. (For internal use only)

Reviewed by Supervisor: _____	Date _____
cc: _____	
Inter-office Referral: 1) _____ 2) _____ 3) _____ 4) _____ 5) _____	

s: north watershed unit/forms/inspection form.doc (vrs. 11/22/00)

Construction Storm Water Inspection-10/28/05
Carlsbad Municipal Golf Course, WDID# 937C337203
Carlsbad, San Diego County



Photo 1
Example of Sediment Trap (Facing South)



Photo 2
Example of New Silt Fence on Perimeter (Facing East on College)

Construction Storm Water Inspection-10/28/05
Carlsbad Municipal Golf Course, WDID# 937C337203
Carlsbad, San Diego County



Photo 3
Example Of Exterior Slopes & Roadways Needing BMPs as Part of Action Plan (Facing West on College Ave)