10/11/06

SGI, 2007, V.2

		liameter permeameter, 14.5" I
	(see note below)	
L 1.15	;	
Elevation	K	time is in seconds
0 0.35		elevation is in feet
9 0.25	112.724	
4 0.15	123.8407	
6 0.1	126.1928	
	•	
Elevation	Κ .	
0 · 0.35		
9 0.25	112.724	
4 0.15	118.0537	
9 0.1	124.9266	
Elevation	K	
0 0.45	•	
	i i	
	Elevation 0 0.35 9 0.25 4 0.15 9 0.25 4 0.15 9 0.1 Elevation 0 0.45 5 0.35 4 0.25	0 (see note below) L 1.15 Elevation K 0 0.35 9 0.25 112.724 4 0.15 123.8407 6 0.1 126.1928 Elevation K 0 0.35 9 0.25 112.724 4 0.15 118.0537 9 0.1 124.9266 Elevation K 0 0.45 5 0.35 115.282 4 0.25 113.8037

This test was conducted at piezometer pair 5

369

The permeameter was set on undisturbed riverbed

0.1 121.5349

Sand and silt were piled around the bottom of the permeameter to form a seal

The permeameter was not pushed into the cobbles at all (not able to).

The silt and sand seal came up to approximately 0.3 feet around the outside of the permeameter.

The use of the 6" permeameter was unsuccessful

Exhibit DFG-C-48b

		SG	31, 200°	7, V. 2	
Diamet	er 1.			e 15" diameter permeameter, 14.5" ID)	
Depth					
Static F	River L	1.75		This test was conducted 40-feet downstream of piezometer pair 5	
			•		
Run 1	F1				
Time			K		
	0 2.1	0.55 0.45	2849.194		
	4.5	0.45	2994.808		
	7.8	0.35	3013.984		
	12.5	0.15	3099.21		
	20.6	0.05	3470.726		
Run 2					
Time	Elev	vation	K	•	
	0	0.55		•	
	2	0.45	2991.653		
	4.1	0.35	3286.984	·	
	7.1 11.2	0.25	3311.137		
	11.2 18.1	0.15 0.05	3458.94 3950.108		
	10.1	0.03	3930.100	•	
Run 3					
Time			K	time is in seconds	
	0	0.55		elevation is in feet	
	1.9	0.45	3149.109	K is in feet per day	
	4	0.35	3369.159		
	6.6	0.25	3561.981		
	10.5	0.15	3689.536		
	18.2	0.05	3928.404		
Run 4					
Time	Flo	/ation I	K		
THE	. 0	0.55	•		
	1.9	0.45	3149.109	·	
	4.2	0.35	3208.723		
	7.5	0.25	3134.543		
	12.4	0.15	3124.204		

This test was conducted at piezometer pair 5

20

10/12/06

The permeameter was dug 1-foot into the riverbed

0.05 3574.848

The inside of the permeameter was void down to the base of the permeameter

(i.e. river bed material was not replaced into the permeameter)

Exhibit DFG-C-48c

10.	/12/06	SGI, 200	7, V.2
Diame Depth Static I		208333 (this was t 1 (see note 1.75	he 15" diameter permeameter, 14.5" ID) below) This test was conducted 40-feet downstream of piezometer pair 5
Run 1 Time	Elev 0 19 41 65 92 123 159 210	vation K 0.85 0.75 765.580 0.65 760.407 0.55 778.325 0.45 803.395 0.35 838.368 0.25 894.48 0.15 959.949	7 6 8 4 4
Run 2 Time	Elev 0 25 51 80 114 156 211	vation K 0.76 0.65 726.8 0.55 736.98 0.45 761.3213 0.35 790.4614 0.25 828.3092 0.15 893.7568	5 3 4 2
Run 3 Time	Elev 0 30 60 94 134 182 245	vation K 0.75 0.65 554.3562 0.55 600.7522 0.45 631.5573 0.35 660.9947 0.25 701.5216 0.15 763.4421	2
Run 4 Time	0 32 67 106 152 208 280	ration K 0.75 0.65 519.7089 0.55 537.9871 0.45 560.0603 0.35 582.719 0.25 613.8314 0.15 668.0118	

This test was conducted at piezometer pair 5
The permeameter was dug 1-foot into the riverbed
The riverbed material was placed back inside the permeameter