



Diversion To Offstream Storage Structure
In Oak Flat Creek - 0.7cfs flowing over



Picture during revisit - Structure has been removed
In Order To Recut To Conform to By-Pass Requirements